



- ◆ Groundwater Monitoring Location
 - * Owner Installed Radon Mitigation System
 - 7 µg/L DCE PLUME OUTLINE (2001)
 - Hydrologic Features
- PARCEL OUTLINE**
- 1768 PS1/3 Street Address Sampling Frequency
- IR Access Not Granted For Initial Testing
 - C Homeowner Considering System
 - M Homeowner Considering System Upgrade
 - MR Mitigation System Refused
 - VR Verification Sampling Refused
 - PR Performance Sampling Refused
 - SO* System Operation Inspection Location
- MONITORING STATUS**
- Mitigation System Exhaust Air Testing Location
 - Verification Monitoring Location
 - Performance Monitoring Location
 - STOP Mitigation and Monitoring Discontinued with CDPHE Approval

REDFIELD SITE

Denver, Colorado

AIR MONITORING PROGRAM STATUS

(as of the END of 2ND QTR 2010)

BASE MAP SOURCE: THIS MAP WAS DERIVED FROM AERIAL PHOTOGRAPHY AND IS NOT INTENDED TO BE A LEGAL SURVEY