



- ◆ Groundwater Monitoring Location
- * Owner Installed Radon Mitigation System
- 7 µg/L DCE PLUME OUTLINE (2001)
- Hydrologic Features
- PARCEL OUTLINE
- 1768 PS1/3 Street Address Sampling Frequency
- ANG Access Not Granted For Initial Testing
- C Homeowner Considering System
- M Homeowner Considering System Upgrade
- MR Mitigation System Refused
- VR Verification Sampling Refused
- PR Performance Sampling Refused
- SO* System Operation Inspection Location
- MONITORING STATUS
- Verification Monitoring Locations - Temporarily Retained
- Bedrock Remedy Enhanced Monitoring Locations
- Mitigation System Exhaust Air Testing Location (Phase 3)
- Verification Monitoring Location - No Change in Frequency
- Performance Monitoring Location
- Confirmation Testing In Progress (Phase 3A)
- STOP Mitigation and Monitoring Discontinued in Phase 1 or 2

REDFIELD SITE

Denver, Colorado

AIR MONITORING PROGRAM STATUS

BASE MAP SOURCE: THIS MAP WAS DERIVED FROM AERIAL PHOTOGRAPHY AND IS NOT INTENDED TO BE A LEGAL SURVEY