

Information Repository

This Information Repository contains key documents related to the Redfield /Brown contamination investigation and cleanup. Due to space limitations it does not contain all of the relevant documents. To review all the public documents please call the Colorado Department of Public Health & Environment at (303) 692-3331 and make an appointment to review the material any weekday between 8:00 - 5:00.

The Abridged Index

Redfield/Brown Site Documents Available at Virginia Village Library

Updated

4th Qtr 2006 & 1 st Qtr 2007 Water Quality Monitoring Data Volumes I, II, and III	May 31, 2007
Phase 2 Results Implementation of New 1,1-DCE Indoor Air Action Level Work Plan	April 5, 2007
2 nd Half 2006 Remedial Assessment Report	March 24, 2007
Off-Site Investigation Work Plan Weathered Bedrock Remedy	July 12, 2007
Revised On-Site Corrective Measures Work Plan	July 12, 2007
2 nd Half Remedial Assessment Report	March 28, 2005
Work Plan for Implementation of New 1,1DCE indoor Air Action Level	January 21, 2005
Supplemental Indoor Air Assessment Report for TCE	January 26, 2005
Additional Soil Investigation Report	August 22, 2003
Preliminary Bioremediation System Design Report	June 24, 2003
East Field Soil Investigation Report Redfield Compliance Order No. 99-01-25-01	June 12, 2003
Phase 1 On-Site Corrective Measures Work Plan	June 6, 2003
Dennis L Snyder, Letter, Brown Group Retail Inc.	January 22, 2003
Analysis of Diagnosed vs. Expected Cancer Cases in the Vicinity of the Redfield Plume Area in Southeast Denver County	1979 - 1999
Analysis of Birth Defect Date in the Vicinity of The Redfield Plume area in Southeast Denver	1989 - 1999
Off-Site Corrective Measures Work Plan	September 30, 2002
Quality Assurance Project Plan	March 4, 2002
Supplemental On-Site Soil Assessment Report Southeast Corner of Redfield Building	June 4, 2002
Off-Site Groundwater Characterization Report Volume 1, Volume 2, Volume 3.	March 21, 2002
Site Inspection Analytical Results Report Cherry Creek Plume – Denver County, CO	March 20, 2001
North Cherry Creek Groundwater Investigation	September 19, 2001
On-Site Outdoor Soil Characterization Report Volume 1 (Text, Figures and Appendix A Through E / Volume II Appendix F Through H)	August 13, 2001
Redfield Riflescopes, Inc. Report of a Site Assessment to Determine the Source of Contamination at the Holly LUST Trust Site	December 22, 1999
Current Fact Sheets	February 2001
LUST site Assessment at Holly & Jewell	December 22, 1999
Design Report Groundwater Containment System Interim Corrective Measure	October 18, 1999
Letter to Lloyd E. Brunkhorst Re: Redfield Rifle Scopes EPA ID COD056828940	September 3, 1999
Status of Blower Mitigation Systems	August 31, 1999
Interim Corrective Measures Work Plan for Groundwater	August 24, 1999
Groundwater Characterization Report	April 1999
Community Relations Plan	March 1999
Integrated Corrective Action Process	March 1, 1999
Additional Voluntary ground water Investigations	February 2, 1999
Preliminary Evaluation of CDOT Region 6 Headquarters Facility Impacts on off-site Ground Water/Indoor Air Quality	August 25, 1998

Questions and Answers about 5800 E. Jewell Fact Sheet	June 16, 1998
Chemicals in Indoor Air Fact Sheet	June 16, 1998
Chemicals in Indoor Air Presentation	June 16, 1998
Compliance Order 98-05-19-02	May 1998
5800 E Jewell Avenue Fact Sheet	March 1998
Letter to (Dave Holm)	December 19, 1996
Letter to Water Quality Control Division	July 18, 1994
Assorted Chemical Fact Sheets from ATSDR	1989 & 1990